

# Optical Return Loss testing using KI 7340 series Loss Tester



**Kingfisher International PTY LTD**

[www.kingfisher.com.au](http://www.kingfisher.com.au)



# General feature summary


---



- **No warm up:**  
Two-Way Loss, Source, Meter & ORL tester
- **Autotest**
- Large memory
- 190 - 360 hr battery life
- KITS™ software for testing/reporting/recording.
- ORL with 65 dB range
- Interchangeable optical connectors. SFF styles available
- Test tone generator



# Return Loss Testing Fundamentals



Return Loss is measured using the Optical Continuous Wave Reflectometer (OCWR) method. This gives a single combined reading of all accumulated reflections at the point of measurement.

This method is accurate, and suitable for acceptance testing.

This ORL reading will be dominated by the largest reflection in a system. So it is important to reduce stray reflections prior to testing.



# Important Issues for ORL Testing

---

Staff performing ORL testing will need to learn about how connectors, fiber ends and other devices affect return loss.

This is not shown here. This discussion shows how to use the instruments.


For general information on return loss in fibre systems, please visit [www.kingfisher.com.au](http://www.kingfisher.com.au), Application Note A6.



# ORL Test - Method 1

---

1. **Autotest** used with two instruments automatically performs **pass / fail** ORL testing from both ends of a link, integrated into the two-way loss test, eg *no extra effort or training!* This is not discussed further here.






# ORL Test - Method 2

---

2. Manual ORL testing uses one instrument. **This is the method discussed here.** It has various additional features, and requires a skilled operator.






# Keypad Location



Press "SHIFT", hidden keypad becomes


Hidden keypad





# 1. The Screen After Turning On

---



Press **"Return Loss"**  
for ORL meter

The connector should be clean.







## 2. ORL Meter

For **single mode** fiber:  
using Mandrel single mode fiber low  
reflection termination

For **multimode** fiber:  
using OPT704A multimode fiber low  
reflection termination



Selected  
wavelength

"RL" = "Return Loss"  
in dB


Press "- +"  
to select wavelength

**Lo** = out of testing range




# Low reflection termination

Single mode



Mandrel diameter  $\cong$  5 mm  
Wrap > 5 times

Multi mode



OPT704A multimode fiber low reflection termination



# Advanced Operation

---


To improve testing accuracy:

- When performing measurements at levels close to unwanted residual back reflections: **ORL Zero function.**
- To compensate for unwanted forward attenuation in a test set-up: **UCAL mode**



# ORL Zero function

## Step 1: Set up minimal ORL condition




The ORL zero function compensates for residual reflections, and enables measurements up to 10 dB lower than the residual reflection level.

Repeat the set-up function whenever the residual ORL changes.



# ORL Zero function

## Step 2: Record ORL noise floor (NF)




ORL noise floor (NF) = -54.7 dB



# ORL Zero function

## Step 3: Measure ORL



Using **ORL Zero** function can expand measurement range further 10 dB.


In above example  
ORL noise floor = -54.7 dB

Measurable ORL:  
 $-(54.73 + 10) \text{ dB} = -64.7 \text{ dB}$



# User Calibration Mode (UCAL)

## Step 1



This method is to compensate for attenuation in the test jigs.

A known optical reference condition should be used to calibrate the instrument and Test Jig.

A known optical reference condition could be:

- A new, clean, PC connector end, which will provide -14.65 dB back reflection
- A gold flashed end providing 0 dB back reflection



# User Calibration Mode (UCAL)

## Step 2

Using Shift

SHIFT DEFAULTS RETURN LOSS  
NF SET RL ADJ

CANCEL SET

Shift  
Source on 1310<sub>nm</sub>  
- 14.65 dB RL  
0.85  
Menu Hold

1. Push "SHIFT"  
2. Push "RL ADJ"  
3. Push "- +" to adjust display value  
4. Push "SET"

Stored UCAL offset factor displayed here


- +





# User Calibration Mode (UCAL)


## Step 3



The ORL reading is the DUT reflection.




# Restore Default settings



Resets both the ORL zero function and UCAL to default settings.



# MEMORY & KITS™



ORL results can be stored in the same way as power meter results. KITS™ displays the ORL results separately for each instrument.



# KITS™ Testing/Recoding/Reporting Software

Used for manufacturing environment

Microsoft Excel - manufacture1

Company Logo here

### Loss Testing Report

3.01U

Manual data entry cells  
Programmed cells  
Protected cells. Can't be changed

Job No:	Job101	Project:	OEM-SC-PC	Date:	06-Jan-2004
Subject:		Stage:		Report/File No:	R-080104-001
Section:		Duct:		Comment:	
Circuit ID:		Cable:		Drawing No:	
Route:		Sheath:		Other:	
	Terminal ID	Sheath ID	Source S/N	Meter S/N	Operator Name
"A"	A			9159	Darren Smith
"B"	B				

Fibre No	1 <sup>st</sup> Wavelength, nm								2 <sup>nd</sup> Wavelength, nm								Pass/ Fail	Min. margin (db)
	0.00								1550									
	Pass / Fail Link Loss, dB								0.30									
	Pass / Fail ORL Loss, dB								-35.00									
Ref level dBm		2nd value dBm		Link loss dB		ORL loss dB		Ref level dBm		2nd value dBm		Link loss dB		ORL loss dB				
A	B	A	B	A to B	B to A	Average	A	B	A	B	A to B	B to A	Average	A	B			
1									-7.07	-7.16			0.09		-35.74		Pass	0.21
2									-7.07	-7.16			0.09		-35.68		Pass	0.21
3									-7.07	-7.16			0.09		-35.68		Pass	0.21
4									-7.07	-7.16			0.09		-35.68		Pass	0.21
5									-7.07	-7.15			0.08		-35.69		Pass	0.22
6									-7.07	-7.15			0.08		-35.69		Pass	0.22
7									-7.07	-7.15			0.08		-35.67		Pass	0.22
8									-7.07	-7.12			0.05		-36.83		Pass	0.25
9									-7.07	-7.13			0.06		-36.83		Pass	0.24
10									-7.07	-7.13			0.06		-36.81		Pass	0.24
11									-7.07	-7.25			0.18		-36.80		Pass	0.12
12									-7.07	-7.82			0.55		-36.80		Fail	
13									-7.07	-7.13			0.06		-36.79		Pass	0.24
14									-7.07	-7.13			0.06		-36.73		Pass	0.24
15									-7.07	-7.13			0.06		-36.72		Pass	0.24
16									-7.07	-7.14			0.07		-36.72		Pass	0.23
17									-7.07	-7.13			0.06		-36.72		Pass	0.24
18									-7.07	-7.13			0.06		-36.73		Pass	0.24
19									-7.07	-7.14			0.07		-36.74		Pass	0.23
20									-7.07	-7.14			0.07		-36.75		Pass	0.23
21									-7.07	-7.14			0.07		-36.83		Pass	0.23
22									-7.07	-7.14			0.07		-36.83		Pass	0.23
23									-7.07	-7.15			0.08		-36.83		Pass	0.22
24									-7.07	-7.14			0.07		-36.82		Pass	0.23
25									-7.07	-7.14			0.07		-36.81		Pass	0.23
26									-7.07	-7.15			0.08		-36.82		Pass	0.22
27									-7.07	-7.15			0.08		-36.81		Pass	0.22

Loss Testing / Data Logging / Label Printing / Meter reading